

ROCK CANDY

High Performance Gloss Floor Coating *Capa Para Pisos De Alta Ejecucion*

This product can be used to replace any water based polymer floor finish. Adapts to all types of flooring, such as vinyl, terrazzo, marble (glazed and honed), quarry tile, ceramic, brick, concrete, rubber, and sealed wood.

May be applied to most unsealed surfaces. This formula seals and finishes.

The initial shine is excellent. For a brighter shine you may spray buff or burnish. This finish may be deep scrubbed and recoated as needed, or burnished to extend its appearance.

RECOMMENDED USES:

- Supermarkets
- Food Service Facilities
- Mega Retail Outlets
- Department Stores
- Malls
- Hospitals
- Schools

BENEFITS:

- Crystal Clear Film
- Blackmark Resistant
- Dirt Resistant
- Wear Resistant
- Burnishable
- Non-Yellowing
- High Solids

SPECIAL INSTRUCTIONS:

- Apply **ONLY** on clean, dry floors.
- Allow ample drying time between coats.
- Dust mop and damp mop daily.
- Burnish for brightest shine

DIRECTIONS FOR USE:

Read and understand MSDS (Material Safety Data Sheet) before using this product.

Stripping and Re-Coating Procedures:

1. Dust Mop entire area to be stripped. Remove gum labels and sticky waste with a scraper.
2. Place "Wet Floor" signs around area to be stripped.
3. Dilute recommended stripping solution according to label directions.
4. Liberally apply stripping solution to the floor. Allow product to remain on surface for 6-8 minutes.
5. Manually scrub all corners and edges that the machine can not reach.
6. Scrub the floor with a machine equipped with a pad or brush. Do Not allow stripping solution to dry onto floor. If this occurs, re-wet surface with stripping solution and scrub.
7. Pick up the stripping solution with a wet vac.
8. If a "Rinse Required" stripper was used, liberally apply clean rinse water to area just stripped. Recover with a wet pick up vacuum and proceed to Step 9. If a "Rinse Free" stripper is used proceed to Step 9.
9. Damp mop area including all corners and edges with clean water. Allow floor to air dry thoroughly.

Scrub and Re-Coating Directions:

1. Dust Mop entire area to be scrubbed. Remove gum labels and sticky waste with a scraper.
2. Place "Wet Floor" signs around area to be scrubbed.
3. Dilute recommended scrubbing solution according to label directions.
4. Liberally apply scrubbing solution to the floor. Allow product to remain on surface for 6-8 minutes.
5. Manually scrub all corners and edges that the machine can not reach.
6. Scrub the floor with a machine equipped with a pad or brush. Do Not allow scrubbing solution to dry onto floor. If this occurs, re-wet surface with stripping solution and scrub.
7. Pick up the scrubbing solution with a wet vac.
8. Damp mop area including all corners and edges with clean water. Allow floor to air dry thoroughly.

Directions for Coating with ROCK CANDY:

1. Pre-soak finish mop in clean, cold water to remove lint.
2. Pour **ROCK CANDY** into a clean bucket equipped with a wringer.
3. Submerge the mop into finish and wring out until drip free.
4. Frame off an area by drawing the mop in a straight line 4 inches out from all edges.
5. Fill in framed section applying finish in a figure 8 pattern. Re-wet mop as needed to apply **ROCK CANDY** at the rate of 2000 square feet per gallon.
6. Follow these procedures and apply first coat of **ROCK CANDY** to the entire floor and allow to air dry thoroughly.
7. Apply a second coat and all additional coats of finish following procedures outlined in Steps 4 thru 6. For final coat only, apply finish up to all edges and allow to dry.