

# PALACE SENTRY

## Ultra High Performance Floor Coating *Capa Para Pisos De Alta Ejecucion*

**PALACE SENTRY** represents the very latest in polymer technology. It combines excellent durability and gloss with a very clear, non yellowing film that is easily applied and levels very well. Burnishing will greatly enhance it's gloss and durability.

**PALACE SENTRY** is ideal for use in all high traffic areas where the highest level of maintenance and appearance is required.

Engineered for safety, this finish meets or exceeds UL and CSPA standards for coefficient of friction (ASTM-D-2047-69) 0.5 minimum.

### **RECOMMENDED USES:**

- Supermarkets
- Malls and Retail Stores
- Hospitals/Health Care Facilities
- Schools
- Prestigious Office Buildings

### **BENEFITS:**

- Excellent Clarity
- Levels Easily
- Self Sealing
- Excellent Durability
- Dries Quickly
- High Solids

### **SPECIAL INSTRUCTIONS:**

#### **PROTECT FROM FREEZING**

### **DIRECTIONS FOR USE:**

#### **STRIPPING:**

1. Place **WET FLOOR** signs around area to be stripped. Scrape up gum and other sticky residue. Dust mop entire area to remove all loose soil.
2. Strip floor using **Free N' Easy** or **PHASE 1** according to label directions.
3. Apply 3 to 4 coats of **Palace Sentry** using a clean mop. Apply at the rate of 2000 square feet per gallon. Apply 20-45 minutes of drying time between each coat of finish depending on drying conditions. (DO NOT Contaminate finish mop with cleaner or stripper.)

#### **DAILY MAINTENANCE:**

1. Place **WET FLOOR** signs around area to be cleaned. Scrape up gum and other sticky residue. Dust mop entire floor to remove all loose soil.
2. Dilute neutral floor cleaner according to label directions for daily maintenance.
3. Clean floors by hand mopping or auto scrubbing.
4. Floors may be burnished using electric, battery or propane burnisher. **NOTE: DO NOT** pour unused finish back into container. **PROTECT FROM FREEZING.**

#### **RECOATING:**

1. Place **WET FLOOR** signs around area to be cleaned. Scrape up gum and other sticky residue. Dust mop entire floor to remove all loose soil.
2. Dilute neutral floor cleaner according to label directions for recoating procedures.
3. Scrub floor with rotary floor machine or auto scrubber equipped with scrub pad or brushes.
4. Apply 1-2 coats of Palace Sentry using a clean mop. Apply at the rate of 2000 square feet per gallon.
5. Allow 20-45 minutes of drying time between each coat of finish, depending on drying conditions.