

PEPCO FREEZE

Freezer and Locker Cleaner *Limpiador De Congelador y Locker*

A ready-to-use wall and floor cleaner for food lockers, walk-in freezers and other sub-freezing areas. Resists freezing to -40°F . Aids in melting ice formations. Use with conventional or automatic scrubbers.

PEPCO FREEZE meets all of the known requirements for use in federally inspected meat and poultry plants as a cleaning compound in product category A5. The A5 rating (as given in the final printing of the USDA's "List of Proprietary Substances and Non Food Compounds") is defined as: "Floor and wall cleaners for subfreezing temperatures. - When used in areas with sub-freezing temperatures, potable water rinsing is not required following use provided that the solution and solubilized soil are effectively removed by wiping or wet vacuuming." This product was previously authorized by the USDA for use in this same category at the final printing of their "List of Proprietary Substances and Non Food Compounds".

This product may be diluted 1 to 1 when used in areas where the temperature is above 0°F . At these temperatures a potable water rinse is required.

RECOMMENDED USES:

- Walk-In Freezers
- Frozen Food Lockers
- Commercial Cold Storage Facilities

BENEFITS:

- Meets USDA Requirements for Use
- Ready-To-Use
- Resists Freezing to -40°F . Rinse is NOT required
- Dilutable at temperatures above 0°F

SPECIAL INSTRUCTIONS:

FLAMMABLE. HARMFUL OR FATAL IF SWALLOWED.

- During cleaning operation, take adequate measures to maintain food at required Health Department temperature levels.

DIRECTIONS FOR USE:

Equip machine with aggressive brush, such as wire, and fill supply tank with ready-to-use cleaner. A double scrub procedure will give best results. Lay down solution with scrubbing action and let set 5 minutes. Then lower squeegee blade, scrubbing again, and pick up solution.

MANUAL CLEANING: Apply cleaner by spray, mop or sponge, followed by aggressive double brushing. Pick up solution with wet-vac or mop.

ROTARY FLOOR MACHINE: Equip machine with aggressive brush, such as steel wire. Spray or mop ready-to-use cleaner on surface, scrub and allow to set 5 minutes. Scrub again and pick up solution with wet-vac or mop.

DILUTION INSTRUCTIONS: This cleaner is intended for use as is, but under conditions of temperature above 0°F can be diluted 1 part cleaner to 1 part water.