

PEX-CARB

Viscous Oven Cleaner

Limpiador Viscoso Para Hornos

Turn every kitchen worker's nightmare into a dream with **PEX-CARB Viscous Oven Cleaner**. Our high-powered cleaner easily sprays or brushes on cooking surfaces and just as easily wipes off, taking burnt grease and foods with it. Surfaces are left shining, with no residue to impart taste or odor to food.

Versatile and fast-acting, **PEX-CARB** cleans not only ovens, grills, griddles, burners and deep fryers, but oily machinery, conveyer belts, ducts, and grease traps as well. Its dense, stable foam clings to vertical surfaces, penetrates and loosens burnt-on or heavily-encrusted accumulations.

Highly effective, **PEX-CARB's** special detergents and water softeners insure optimum performance, no matter how hard your water. And fast! This non-flammable, non-fuming liquid cleans in 3 to 30 minutes, depending upon build-up. If desired, it can be left on ovens and similar surfaces overnight.

RECOMMENDED USES:

- Normal cooking surfaces
- Machinery, ducts and traps where grease and oil accumulate

BENEFITS:

- EASY TO USE—Spray on, wipe off
- FAST-ACTING—3 to 30 minutes
- EFFECTIVE—Performs in even the hardest water
- SAFE—Non-flammable, non-fuming

SPECIAL INSTRUCTIONS:

- THIS PRODUCT CAN DAMAGE the following metals: aluminum, copper, brass, tin, zinc, and galvanized metal. If cleaner accidentally runs or is splashed onto these surfaces, RINSE OFF IMMEDIATELY.

DIRECTIONS FOR USE:

OVENS, GRILLS, ETC.: Use a foam dispenser and apply cleaner solution (see dilution ratio below) to rear wall first, then spray sides, bottom, and front panel. Work foam into heavy soil deposits with a stiff brush. Let cleaner stand on warm surfaces 3 to 15 minutes, cold surfaces 3 to 30 minutes depending on soil build-up. Remove emulsified soil with a wet cloth or sponge. Rinse surface and wipe dry.

MACHINERY: Follow above directions. Rinse foam and soil away completely using hose or sprayer whenever possible to thoroughly clean crevices and hard-to-reach surfaces.

Extremely old and heavy accumulations may require two or more applications for complete removal.

NOTE: This product can etch aluminum, tarnish copper and brass, and attack tin, zinc, and galvanized metal. If cleaner accidentally runs or is splashed onto these metals rinse off immediately.

Light Soil—Dilute 1 part concentrate to 15-20 parts water.

Medium Soil—Dilute 1 part concentrate to 10 parts water.

Heavy Soil—Dilute 1 part concentrate to 3-5 parts hot water.